



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ
ಪಂಚಾಯತ್ ರಾಜ್ ಇಂಜಿನಿಯರಿಂಗ್ ಉಪ-ವಿಭಾಗ, ರಾಮನಗರ.

Email:aeermg123@gmail.com

ಸಂಖ್ಯೆ: ಸಕಾಇಂ/ಪ.ರಾ.ಇಂ.ಉ.ವಿ/ರಾಮ/2023-24

ದಿನಾಂಕ:

To,
Principal
Universal Public school,
BM road, Archakarahalli, Ramanagara-562159.

98
06/6/2023

Sir/Madam

Subject: Issuing of School Building Safety Certificate

Reference: Your letter Dated: **02-06-2023**

With Reference to the above request made by Principal of Universal Public school, BM road, Archakarahalli, Ramanagara-562159 on 02-06-2023. The details of structural stability of the building Block-I, (G+4) Ground Floor, First Floor, Second Floor, Third Floor and Fourth Floor is as follows.

Thus, the Building **Universal Public School, Archakarahalli, Ramanagara – 562159** is verified Physically by VAL Civil Management Consultancy and Laboratories. Based on the present condition of the building and the test NDT result (report enclosed) it is inferred that the existing building G+4 complies with the Stability requirements as expected by the provisions of section 35 of IS 456:2000 (Indian Standard Plain and Reinforced Concrete –Code of Practice, (latest revision).

Hence it is certified that the existing building G+4 is Structurally Stable for running the school, and it is advised to the management to take necessary actions to repair the distress condition which is mentioned in the report.

Enclosed: Inspection Report.

Yours Faithfully

Lavanya
Assistant Executive Engineer
Panchayath Raj Engineering Sub-Division,
Ramanagar.